

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2010 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway			Bank	Unit Miles
Unit No. 01 West Levee			Right	2.72
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/24/2010 - 3/24/2010			
DWR Inspector	John Williamson			
Accompanied By	Larry Kline Sacramento Maintenance			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 West Levee						Right	2.72	03/24/2010 03/24/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	2.71	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.758948 ° -121.667560 °	38.724243 ° -121.665056 °	2 Y
2	0.00	2.71	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.758950 ° -121.667559 °	38.724244 ° -121.665056 °	1 Y
3	0.94	1.82	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.747962 ° -121.660240 °	38.735048 ° -121.660303 °	8 Y
4	1.83	1.83	Earthen Levee	Encroachments	LS	M	Material	38.734811 ° -121.660258 °	38.734811 ° -121.660258 °	5 Y
5	1.85	1.85	Earthen Levee	Encroachments	LS	M	Debris Inspector Comments: debris is concrete box from removed 42" pipe, 20" pipe missing flap gate	38.734574 ° -121.660258 °	38.734574 ° -121.660258 °	6 Y
6	2.38	2.42	Supplemental Survey	USACE Erosion	WS	M	Inspector Comments: 2009: no berm, 2:1 slope, no stability issues, sands and silts, 1.5 ft/s [2009 SiteID:YOL_2-5_R]	38.726897 ° -121.660381 °	38.726394 ° -121.660392 °	3
7	2.53	2.68	Supplemental Survey	USACE Erosion	WS	M	Inspector Comments: 2009: no berm, 2:1 slope, no stability issues, sands and silts, 1.5 ft/s [2009 SiteID:YOL_2-6_L]	38.725506 ° -121.662042 °	38.724386 ° -121.664564 °	9
8	2.63	2.70	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.724800 ° -121.663710 °	38.724230 ° -121.664873 °	4

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72	03/24/2010 03/24/2010	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	2.71
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Tall grasses 12" or taller

johnngw\_s\_20100325\_061.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	2.71
Location	Land Side
Category	Earthen Levee
Item	Vegetation

12" or taller

johnngw\_s\_20100325\_062.jpg



Levee Mile Report Line	3
Start Levee Mile	0.94
End Levee Mile	1.82
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Agricultural ditch at toe of landside levee

johnngw\_s\_20100325\_065.jpg

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 West Levee	Right	2.72	03/24/2010 03/24/2010	John Williamson

Levee Mile Report Line	4
Start Levee Mile	1.83
End Levee Mile	1.83
Location	Land Side
Category	Earthen Levee
Item	Encroachments

scrap metal at toe of landside levee

johngw\_s\_20100325\_066.jpg



Levee Mile Report Line	5
Start Levee Mile	1.85
End Levee Mile	1.85
Location	Land Side
Category	Earthen Levee
Item	Encroachments

old concrete cuvert box at toe of landside levee

johngw\_s\_20100325\_067.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway			Bank	Unit Miles
Unit No. 02 West Levee			Right	1.52
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/23/2010 - 3/23/2010			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 West Levee						Right	1.52	03/23/2010 03/23/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	1.51	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.718981 ° -121.664077 °	38.698792 ° -121.674113 °	2
2	0.00	1.51	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.718981 ° -121.664076 °	38.698792 ° -121.674112 °	1
3	0.08	0.21	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.718005 ° -121.664496 °	38.716140 ° -121.665460 °	4 Y
4	0.47	0.97	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.712813 ° -121.667349 °	38.706018 ° -121.670831 °	3 Y
5	1.15	1.44	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.703681 ° -121.672090 °	38.699637 ° -121.674112 °	5 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52	03/23/2010 03/23/2010	John Williamson

Levee Mile Report Line	3
Start Levee Mile	0.08
End Levee Mile	0.21
Location	Land Side
Category	Earthen Levee
Item	Encroachments

borrow pit and agricultural ditch

johngw\_s\_20100324\_050.jpg



Levee Mile Report Line	4
Start Levee Mile	0.47
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Agricultural ditch

johngw\_s\_20100324\_051.jpg



Levee Mile Report Line	5
Start Levee Mile	1.15
End Levee Mile	1.44
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Agricultural ditch

johngw\_s\_20100324\_052.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

Tuesday, July 06, 2010 15:34

**FINAL DATA**

Page 2 of 3



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 West Levee	Right	1.52	03/23/2010 03/23/2010	John Williamson

Levee Mile Report Line	5
Start Levee Mile	1.15
End Levee Mile	1.44
Location	Land Side
Category	Earthen Levee
Item	Encroachments

agricultural ditch and pump

johngw\_s\_20100324\_053.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway				Bank	Unit Miles
Unit No. 03 West Levee				Right	1.48
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	3/23/2010 - 3/23/2010				
DWR Inspector	John Williamson				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 West Levee						Right	1.48	03/23/2010 03/23/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.78	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: North end of Cache Creek Weir	38.698584 ° -121.674103 °	38.687303 ° -121.673710 °	1 Y
2	0.00	0.78	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: North end of Cache Creek Weir	38.698584 ° -121.674103 °	38.687303 ° -121.673710 °	2 Y
3	1.20	1.47	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.681250 ° -121.672906 °	38.677260 ° -121.672802 °	4
4	1.20	1.47	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.681250 ° -121.672907 °	38.677260 ° -121.672802 °	3

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 West Levee	Right	1.48	03/23/2010 03/23/2010	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.78
Location	Land Side
Category	Earthen Levee
Item	Vegetation
vegetation, grasses mow or burn	
johnngw_s_20100324_055.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.78
Location	Water Side
Category	Earthen Levee
Item	Vegetation
vegetation grasses mow or burn	
johnngw_s_20100324_054.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway			Bank	Unit Miles
Unit No. 04 West Levee			Right	3.61
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/24/2010 - 3/24/2010			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 West Levee						Right	3.61	03/24/2010 03/24/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	3.60	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.574608 ° -121.638910 °	38.523892 ° -121.631444 °	1 Y
2	0.00	3.59	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.574606 ° -121.638909 °	38.523923 ° -121.631436 °	2 Y
3	0.57	0.57	Earthen Levee	Encroachments	CR	M	Material Inspector Comments: railroad tracks being repaired; material blocking levee crown no access across tracks and it appears that work is not being performed at this time.	38.566349 ° -121.638873 °	38.566349 ° -121.638873 °	5 Y
4	1.78	2.70	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.550387 ° -121.631257 °	38.536958 ° -121.631450 °	3 Y
5	2.76	3.60	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.536100 ° -121.631425 °	38.523807 ° -121.631535 °	4 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61	03/24/2010 03/24/2010	John Williamson

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	3.60
Location	Land Side
Category	Earthen Levee
Item	Vegetation
vegetation 12" or taller	
johngw_s_20100325_072.jpg	



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	3.59
Location	Water Side
Category	Earthen Levee
Item	Vegetation
waterside vegetation	
johngw_s_20100325_073.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.57
End Levee Mile	0.57
Location	Crown
Category	Earthen Levee
Item	Encroachments
changing railroad ties out; crown blocked	
johngw_s_20100325_074.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61	03/24/2010 03/24/2010	John Williamson

Levee Mile Report Line	4
Start Levee Mile	1.78
End Levee Mile	2.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments

ag drain LM 1.78-2.70

johngw\_s\_20100316\_043.jpg



Levee Mile Report Line	4
Start Levee Mile	1.78
End Levee Mile	2.70
Location	Land Side
Category	Earthen Levee
Item	Encroachments

landside toe

johngw\_s\_20100325\_075.jpg



Levee Mile Report Line	5
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments

ag drain LM 2.76-3.60

johngw\_s\_20100316\_044.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Sacramento Maintenance Yard West Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 West Levee	Right	3.61	03/24/2010 03/24/2010	John Williamson

Levee Mile Report Line	5
Start Levee Mile	2.76
End Levee Mile	3.60
Location	Land Side
Category	Earthen Levee
Item	Encroachments

landside toe

johngw\_s\_20100325\_076.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected